


PART-II

(To be filled by the S.D.E of P.W.D. (B & R) Department /Panchayati Raj.)

Name of the School DAV PUBLIC SCHOOL, SAMANA

Block SAMANA . Disttt. Patiala.

- a) I have visited the above mentioned school as on 19.03.2021
- b) In case any addition alteration or expansion and modifications to this building is to be carried out then it will be carried out under the supervision of a technically qualified engineer and this certificate may again be obtained after the completion from the used signed.
- c) In case the school building is effected by flood there is a settlement of walf/foundations or dislogging of roofs etc. immediate report/inspection of the undersigned be arranged to check the stability and safety of the building.
- d) The building can be safety occupied for normal used upto 31.03.2022 as mentioned in the performa who is entirely responsible for the structural safety, the School building has visually been inspected and the same seems to be in safe and for use under normal conditions.


Assistant Engineer
Panchayati Raj P.W. Sub Div
Samana(Patiala)