



**Sub Divisional Engineer,  
Water Supply and Sanitation, Sub Division, Samana.**  
Email:- sdesamana@gmail.com

---

To,

The Principal,  
DAV Public School,  
Samana.

No. 1107

Date: 29/12/25

**Sub:- Regarding Water and Sanitation Certificate.**

**Ref. No.:-** Your School letter No. DAV SAMANA/271/2025-26 dt. 12.11.2025.

Reference to the above cited subject that in your school the number of urinals & latrines for males and females are adequate, neat and clean. The source of water supply is through submersible pump. As per water sample test report received from Trade Waste and Effluents Research Unit (Regional Lab), Patiala vide letter No. TWERU/2526/00594 dt. 16.10.2025 drinking water provided in your school is totally safe and general sanitation is satisfactory. This is for your information and necessary action.

DA:- Water Sample Test Report.

  
**Sub Divisional Engineer,  
W/S & Sanitation Sub Division,  
Samana.**